Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0099**

Resource Identification

Property Name(s): ..... House, Route 635 {Function/Location}
Property Date: 1850
Address(s): ..... Route 635 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Exterior end	Brick	
Porch	Porch - 1-story, 3-bay	Wood	Porch - Columns, Square
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Roof	Roof - Gable	Metal	Roof - Standing Seam

WUZIT Count:

No.	Wuzit Types	Historic?
3	Other	Undetermined
1	Single Dwelling	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Other
Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: .....
Description: Architecture Summary: 3 frame outbuildings. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Single Dwelling
Est. Date of Construction: .... 1850 ca {VDHR Survey File}
Accessed? .....
Primary Resource? ..... Yes
Number of Stories: 2.0
Architectural Style: ..... Greek Revival
Condition: .....
Interior Plan Type: ..... Central Passage, Single Pile
Threats to Resource: .....
Description: Architecture Summary: Porch has hipped roof, is early 10th century addition. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: I-house End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Report generated 11/17/04

Significance Statement: Typical mid-19th century frame I house in area 1

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: ..... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-99
Negative no(s).

City/Town/Village/Hamlet Windsor Vicinity
Street address or route number Rte. 635, .5 mi. east Rte. 610
Historic name

County Isle of Wight
U.S.G.S. Quad Windsor
Common name

Present use Dwelling
Original use Dwelling

Building Style Greek Revival
Building Date(s) ca. 1850

1. Construction Materials

- ☒ wood frame
- ☐ brick
  - bond: ☐ English ☐ Flemish ☐ ____-course American ☐ stretcher ☐ other ____
- ☐ stone
  - ☐ random rubble
  - ☐ coursed rubble
  - ☐ ashlar ☐ dressed ☐ rock-faced
- ☐ log:
  - ☐ squared ☐ unsquared
  - notching: ☐ V-notch ☐ half dovetail ☐ saddle ☐ full dovetail ☐ square ☐ diamond
- ☐ concrete block
- ☐ terra cotta
- ☐ steel frame
- ☐ other ____

2. Cladding Material

- ☒ weatherboard
- ☐ vertical siding
- ☐ board & batten
- ☐ shingle: ☐ wood ☐ asbestos ☐ asphalt
- ☐ bricktex
- ☐ other ____
- ☐ composition siding
- ☐ stucco
- ☐ aluminum or vinyl siding
- ☐ cast iron
- ☐ sheet metal
- ☐ enameled metal
- ☐ glass



3. Stories (number) 2
   ☐ low basement ☐ raised basement

4. Bays (number): front 3 side (church) ____
   ☒ symmetrical ☐ asymmetrical

5. Roof Type
   - ☐ shed ☐ parapet?
   - ☒ gable ☐ pediment? ☐ parapet? ☐ clipped end? ☐ cross gable? ☐ central front gable?
   - ☐ hipped ☐ pyramidal?
   - ☐ mansard
   - ☐ false mansard
   - ☐ gambrel
   - ☐ flat ☐ parapet?
   - ☐ roof not visible
   - ☐ other ____

6. Roofing Material
   - ☐ shingle ☐ composition (asphalt, asbestos, etc.) ☐ wood
   - ☒ metal ☒ standing seam ☐ corrugated ☐ pressed tin (simulated shingles)
   - ☐ tile ☐ pantile ☐ flat ☐ glazed
   - ☐ slate
   - ☐ not visible

7. Dormers (number): front ____ side ____
   ☐ gable ☐ pediment? ☐ shed ☐ hipped

8. Primary Porch
   style ____
   stories 1
   levels 1 bays 3
   materials wood, standing seam metal
   description and decorative details
   Hipped roof, square wood columns, exposed rafter ends, early 20th-C addition.

9. General supplementary description and decoration: Deep overhang of roof on gable ends, cornice returns. Six-over-six sash. Unbeaded weatherboards.

10. Major additions and alterations: Early 20th-C 2-room, one-story rear ell.

11. Outbuildings:

12. Landscape Features: Set on the edge of a large field, bordered by woods.

13. Significance: Typical mid-19th-century frame I house in area.

Surveyed by: Willie Graham Date: 7/4/90



FIGURE 9
Architectural Resources Identified During Survey